



SERVICE MEMO

14-10-2024

Dispenser(s): *Omni line*
Title: *Clip for T-piece*

Background:

There have been reported issues with the outlet hose that is coming loose from the T piece. This is caused by missing ribs on the T-piece. Because the machine is reaching the end of production, a tool modification is too expensive.

Action/alternative solution:

Place a hose clip on the hose as shown below:
55121933 HOSE CLIP (094329)



Name: J. Verdam

