

|  |                                |
|--|--------------------------------|
| <b>T.I. no.: 2018 - 14</b><br>Updated: - | <b>Topic: New power supply</b> |
|--|--------------------------------|

|                                     |                 |                              |
|-------------------------------------|-----------------|------------------------------|
| <b>Date: 11.07.2018</b>             | <b>Priority</b> | <b>Need for action</b>       |
| <b>Affected machines: SCA P</b>     | High            | As soon as possible          |
| <b>From serial number: 1828.../</b> | X Medium        | On next visit to the machine |
| <b>As of date: -</b>                | Low             | X FYI only                   |

## NEW POWER SUPPLIES

Previously used power supply 068588 no longer complies with the valid standards of the US market and is being replaced with three new power supplies.

|  |   |
|--|---|
|  | <b>IMPORTANT</b><br>The new power supplies require new software version 6.10 and do not work with older versions! |
|--|---|

- 068720 for USA
- 068722 Asia
- 068721 remaining market

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.