

<b>T.I. no.:</b> 2021-17 <b>Updated:</b> -	<b>Topic:</b> Software SCP V2.84
---	----------------------------------

<b>Date:</b> 17.06.2021	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines:</b> SCP	High	As soon as possible
<b>From serial number:</b> 2110../	X Medium	X On next visit to the machine
<b>As of date:</b> -	Low	FYI only

## IMPROVEMENTS

### Software bug fixes

With software version 2.8.4, the errors listed below have been eliminated.

- Initialisation error: After descaling, the brewer is no longer in position (insertion position).
- When commissioning an SCP with a water tank: Error message "Water tank empty" was displayed randomly.
- Failure: No timeout possible when feeding the steam boiler.