

T.I. No.: 2023-19 Updated: -	Topic: Schaerer Barista - Software-Version 3.0.4
---	---

Date: 29.08.2023	Priority	Need for action
Affected machines: Schaerer Barista	High	As soon as possible
From serial number: -	X Medium	X On next visit to the machine
As of date: immediately	Low	FYI

SOFTWARE UPDATE INFORMATION

The software V3.0.4 replaces the software version V3.0.3.

Optimisations

Compared to the software version 3.0.3 there is the following optimization:

- Loading data backups
With software version 3.0.3 it was no longer possible to load data backups from a USB stick onto a machine. If a data backup was loaded, the machine requested a software update from the service.
With the new software version this behaviour was corrected.

Information

If errors should occur during / after the software update, we ask you to send a data backup together with an exact error description via e-mail to <technical-support@schaerer.com>.

During approval testing the following update tests have been carried out successfully:

Model / type	from version	To version
Schaerer Barista – all variants	v.2.4.3, v.2.6.2, v.3.0.3	v.3.0.4

Update power stage version:

If the error 9883 is shown during the update, the firmware update of the power stage must be performed manually.

Menu Service > Service routines > Firmware update power stage

Service Contact

Global Technical Support Team

GBU Professional Coffee Machines

- > Support Hotline: +41 32 681 62 75 (10:00-11:30 CET/ 15:00-16:30 CET)
- > Support E-Mail: technical-support@schaerer.com