

T.I. no.: 2023-11 Updated:	Topic: SKYE Software V4.54.6
--------------------------------------	-------------------------------------

Date: 05.04.2023	Priority	Need for action
Affected machines: SKYE	High	As soon as possible
From serial number: -	x Medium	x On next visit to the machine
As of date: immediately	Low	FYI only

INFORMATION ON SOFTWARE-UPDATE

The new software update V4.54.6 eliminates bugs, optimises the platform software and replaces the software version V4.38.11.

Overview of the most relevant new features

- In-export of 'configuration packages' (which include media packages)
- Powder calibration to facilitate nutritional information for beverages that contain powder
 - > only relevant when using the nutritional information
 - > no effect on the beverage settings
- Blinking of the status lights for five seconds prior outlet rinsing
 - > Frequency (on/off): 250ms
 - > Colour: yellow
- Telemetry feature: remote update of the menu card including all recipes (transfer of individual recipes is currently impossible)
- Utilities (service menu) expanded with 'steam boiler pressure test'
- ProCare: Various cleaning schedule optimisations / Last mile cleaning (with Plug & Clean) enforced / new parameter 'reset pouch counters' in the service menu
- Parameter 'outlet cover' in the 'undetectable' section of the hardware detection
 - > default = 'on' (animation shown during the cleaning)
 - > 'off' for special machine versions (Soul C for the US)

Corrections/fixed issues

- Flavour point cleaning is fully restored
- Control of valve V25 is restored
 - > 3/2 way valve for Super Steam with Best Foam or
 - > 2/2 way valve for Super Steam without Best Foam
- Grinder calibration value was not processed by the software (unless a manual restart was made).

Service Contact

Global Technical Support Team
 GBU Professional Coffee Machines
 > Support Hotline: +41 32 681 62 75 (10:00-11:30 CET/ 15:00-16:30 CET)
 > Support E-Mail: technical-support@schaerer.com