

TYPE NO FB7300	TYPE Coffe Vending Machines	T.I. NO 2013_03				
SERIAL NUMBERS AFFECTED From and including S/N 24011223	ISSUED BY Documentation/N&W Valbrembo					
SUBJECT TASTE IMPROVEMENT		ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action						
Information	X					


HEADLINE

- In order to improve the taste of the machine's beverage, the material of the waste bucket has been change and the insulator of the boiler has been removed.

COMPONENTS CONCERNED



old code waste bucket:

39958900



new codes waste bucket:

258527



Code boiler support :


256518



code gasket:

099844

code insulation 39759100



old code boiler assembly 255873



TECHNICAL INFORMATION

TYPE NO FB7300	TYPE Coffe Vending Machines	T.I. NO 2013_03				
SERIAL NUMBERS AFFECTED	From and including S/N 24011223	ISSUED BY Documentation/N&W Valbrembo				
SUBJECT TASTE IMPROVEMENT	ISSUED FOR (X): <table border="1"><tr><td>Action</td><td><input type="checkbox"/></td></tr><tr><td>Information</td><td><input checked="" type="checkbox"/></td></tr></table>		Action	<input type="checkbox"/>	Information	<input checked="" type="checkbox"/>
Action	<input type="checkbox"/>					
Information	<input checked="" type="checkbox"/>					

MODIFICATION

- The material of the waste bucket has been changed from ABS to self-extinguishing polystyrene
- The boiler insulator **39759100** has been removed and a support boiler (**256518**) + gasket (**099844**) have been introduced in order to maintain the boiler in the right position

REASON

- Taste improvements

REPLACEABILITY

- All the codes are 100% interchangeable.