

TYPE NO FB 7300	TYPE Coffe Vending Machines	T.I. NO 06 - 2015				
SERIAL NUMBERS AFFECTED From and including S/N 50611679	ISSUED BY Documentation/N&W Valbrembo					
SUBJECT NEW AGITATION WIRE FOR COFFEE POWDER	ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td><input type="checkbox"/></td> </tr> <tr> <td>Information</td> <td><input checked="" type="checkbox"/></td> </tr> </table>		Action	<input type="checkbox"/>	Information	<input checked="" type="checkbox"/>
Action	<input type="checkbox"/>					
Information	<input checked="" type="checkbox"/>					


REASON

Breaking of the short agitation wire, used in the dual FB canister assembly


MODIFICATIONS:

The short agitation wire (pre-modification, see picture 1) has been replaced by a stronger agitation wire design (see picture 2).

This new agitation wire is specific for coffee powder and it ensures greater resistance and better dose accuracy.



**Old agitation wire (short)
Picture 1**



**New agitation wire (short)
Picture 2**

The **new agitation wire** spare part code is

259501

The **old agitation wire** spare part code is

39283500 (it is no longer available)

EXCHANGEABILITY:

The new agitation wire can be installed in the machines prior to the above mentioned serial number.