

Type Coffee Vending Machine	Model 9100 - 9200	N° T.I. XX - 2023	
Serial Number 31721031	Subject Flash Memory SOM CHANGE on the Touch Screen	ISSUED FOR (X)	Action Information <input checked="" type="checkbox"/>

REASON:

Due to components shortage

MODIFICATIONS:

A **new flash memory SOM** has been inserted inside the **10" Touch Screen Assembly** used for 9100 and 9200.

✓ The touch screen assembly spare code in not changed: **264505**

Label on the back of
Modified 10" Touch Screen Assembly



Label on the back of
Pre - modification 10" TS Assembly



✓ The introduction of the **new SOM** made it necessary to develop a **new system key rev. 4.0.3-1**.

➤ **Machines concerned by modification from S/N: 31721031**

EXCHANGEABILITY:

New 10" Touch Screen Assembly can be used for machines previous to **S/N** above.

The **new system key rev. 4.0.3-1** is not necessarily to be extended to older generation touch assemblies even if **Key 2** is updated.