

Type Coffee Vending Machine	Model 95	N° T.I. 06 - 2023
Serial Number 24024490	Subject CAPACITIVE KEYBOARD WITHOUT GIGABIT PORT	ISSUED FOR (X) Action Information X

REASON:


Due to shortage of the Gigabit Ethernet modules present on the current capacitive keyboards

MODIFICATIONS:


Since the Ethernet connection is now little used unlike Wifi and 4G solutions, the *Ethernet port* and its *chip* have been removed from the CPU board, contained in capacitive keyboards.

Modified capacitive keyboard (no Gigabit port)

Pre-modification capacitive keyboard




CUP board detail



Ethernet port has been removed

CUP board detail





Ethernet port

Type Coffee Vending Machine	Model 95	N° T.I. 06 - 2023
Serial Number 24024490	Subject CAPACITIVE KEYBOARD WITHOUT GIGABIT PORT	ISSUED FOR (X) Action Information X

Modified CPU board (Bottom view)

Pre-modification CPU board (Bottom view)



Chip removed



Chip

➤ Below the capacitive keyboard **codes** without and with Gigabit port

Capacitive keyboard – 6 selections -no Gigabit port

Spare part code: **265670**

Capacitive keyboard – 6 selections

Spare part code: **261667**

Capacitive keyboard – 10 selections -no Gigabit port

Spare part code: **265671**

Capacitive keyboard – 10 selections

Spare part code: **262040**

➤ **Machines concerned by modification from S/N 24024490.**

EXCHANGEABILITY:

Capacitive keyboards without Gigabit port can be used on machines produced before S/N above.

Code **261667** will be available while stocks last.

Code **262040** is no longer available.