

Type Coffee Vending Machine	Model 9100 - 95	N° T.I. 05 - 2022	
Serial Number 20421288	Subject NEW ACTUATION BOARD	ISSUED FOR (X)	Action Information X

REASON:

Due to the lack of *microprocessors* present on the *actuation board*

MODIFICATIONS:

A **new** *actuation board* is introduced. The main difference between the old and the new actuation board is the microprocessor and the related power supply circuit.

New actuation board Spare code:
265409/SAP 55124915

Pre - modification actuation board
Spare code: **261899/SAP 55120054**



