

| | | | |
|---------------------------------------|--|-----------------------------|--------------------------------|
| Type Coffee Vending Machine | Model OPERA TOUCH | N° T.I. 06 - 2022 | |
| Serial Number 22221615 | Subject RECODING MACHINES WITH NEW BOARD | ISSUED FOR (X) | Action Information X |

REASON:

Due to the lack of "Wi-Fi e Bluetooth" chip


MODIFICATIONS:

A **new** CPU board without "Wi-Fi e Bluetooth" chip has been introduced in production and as spare (temporarily)

Back of the current CPU board with **Wi-Fi e Bluetooth** chip **no more available**



Wi-Fi and Bluetooth chip



Important note: to ensure connectivity functionality, the introduction of a **USB dongle** is being approved. Its introduction and availability will be communicated with a supplementary notice.

- ✓ The **pre - modification CPU Opera Touch board** with "Wi-Fi e Bluetooth" chip, currently not available due to the lack of the component mentioned above, it keeps the spare code: **261137**
- ✓ The **new CPU Opera Touch board** without "Wi-Fi e Bluetooth" chip has the following spare code: **265555 sap 55124947**



| | | | |
|---------------------------------------|--|-----------------------------|-----------------------------|
| Type Coffee Vending Machine | Model OPERA TOUCH | N° T.I. 06 - 2022 | |
| Serial Number 22221615 | Subject RECODING MACHINES WITH NEW BOARD | ISSUED FOR (X) | Action Information X |

➤ Below the list of machines, that have **new codes** because they're supplied with **CPU board** without "*Wi-Fi e Bluetooth*" chip.

| New code | Current code | Description |
|-----------------|---------------------|---------------------------|
| 968062 | 968016 | OPERA TOUCH ESB6-R/DQ JDE |
| 968261 | 968255 | OPERA TOUCH IN7-R/NLQ |

➤ **Machines concerned by modification from S/N: 22221615**