

T.I. no.: 2017 - 03 Updated: -	Topic: Twin Topping partition wall and filling aid
---	---

Date: 27/2/2017
Affected machines: SCV
From serial number: -
As of date: 1/3/2017

Priority	
	High
	Medium
X	Low

Need for action	
	As soon as possible
	On next visit to the machine
X	FYI only

SOLUTION TO THE PROBLEM

Part "060632 Twin Topping filling aid" and part "060631 Twin Topping partition wall" have been modified.
The retaining cam on the filling aid has been reinforced. Installation of the partition wall with filling aid is now easier.

IMPORTANT NOTICE

Both parts are available individually, but please note that the parts are not backwards compatible.


INFORMATION

Both parts are available in the modified version as a set with part number 060663.

ORDERING OPTIONS

- As individual parts:
- Part [060631] Twin Topping SCV partition wall
 - Part [060632] Twin Topping SCV filling aid

As Set => [060663]



(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.