

T.I. no.: 2017 - 12 Updated: -	Topic: SC Soul Software 1.85
--	-------------------------------------

Date: 27.07.2017	Priority	Need for action
Affected machines: SC Soul	High	As soon as possible
From serial number: 1728../	X Medium	X On next visit to the machine
As of date: -	Low	FYI only

NEW FUNCTIONS AND IMPROVEMENTS

The following is an overview of the new functions and fixed errors:

New functions:

- New control panel for changing parameter settings.
- Instruction to check the process speed before descaling.

Improvements

- If the grounds drawer is removed, this is correctly detected during descaling.
- Switch-off rinsings after cleaning are carried out correctly.
- Grinder calibration can be performed without a restart.
- Instruction to insert the grounds container during cleaning does not need to be confirmed.
- Water flow faults are correctly recorded in the fault log.
- Premature heating by the machine when starting rectified.
- Parallel pre-brewing/pre-rinsing during beverage dispensing rectified.
- When the Service menu is opened, the uppermost menu entry is displayed by default.
- Withdrawing the grounds drawer during brewing pressure calibration results in a blockage of the machine. Calibration can be continued correctly after the grounds drawer has been inserted.
- The milk empty message is no longer displayed during descaling.
- Pre-heating/pre-cooling with Best Foam beverages is carried out correctly.
- Machine is not restarted automatically after the coffee and powder system has been cleaned.
- Beverage preselection/basket are deleted when the milk and bean empty message is activated.
- Various texts adapted
- Twin powder container is supported.
- Date of water change is displayed correctly.
- Water filter settings are transferred correctly on update.
- Character can now also be added using the keyboard. There is no need to type in the complete name from the beginning.
- No rinsing when filling the milk hose.
- Beverage can be cancelled on the beverage dispensing display.
- Parameters in the Hardware configuration menu completed.
- If several rinsing processes are pending within 5 minutes, they are all carried out together.
- Repeated switching of the pressure-relief valve if there is a water flow fault rectified.
- Adjustment of the coffee strength is retained even when there is a change to another menu card.
- Incorrect name of hot water dispensing valve and additional water valve corrected.

New control panel

A new control panel has been created to facilitate operation when setting the parameters. The text box must be touched to display the keypad.

