

| | |
|--|--------------------------------------|
| T.I. no.: 2017 - 88 Updated: - | Topic: JDE B0 Software 3.42.0 |
|--|--------------------------------------|

| | | |
|----------------------------------|-----------------|--------------------------------|
| Date: 02.10.2017 | Priority | Need for action |
| Affected machines: JDE B0 | High | As soon as possible |
| From serial number: - | X Medium | X On next visit to the machine |
| As of date: - | Low | FYI only |

NEW FUNCTIONS AND IMPROVEMENTS IN 3.42.0

The following is an overview of the improvements:

Improvements:

- Timeout increased to 50 seconds if a beverage is cancelled with a payment system.
- If the menu item under-counter ground container is selected, the capacity can be reset to 0. Then the warning is no longer displayed. The operator is responsible for not overfilling the grounds container.
- While beverages are being made, the NcFoamer is no longer rinsed.

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.