

T.I. no.: 2018 - 19 Updated: -	Topic: SCClub Software 1.5.6
---	-------------------------------------

Date: 20.08.2018	Priority	Need for action
Affected machines: SC Club	High	As soon as possible
From serial number: -	Medium	On next visit to the machine
As of date: -	X Low	X FYI only

IMPROVEMENTS

The following is an overview of the improvements:

Improvements:

- Multiple brewing error fixed
- Display of remaining usage time when “Please exchange water filter soon...” message appears
- “Cleaning according to time” function removed
- Scroll bars added to various menus

Multiple brewing error fixed

If the multiple brewing function was used, sometimes the machine did not react when starting the next drink or the “No connection to the PC board” message appeared in the display.

The same error image was also reported when the machine had to distribute beverage dispensing between two brewing cycles if the dispensing volume was large.

Display of remaining usage time when “Please exchange water filter soon...” message appears

When the message for water filter exchange appears, the remaining usage time of the water filter is now also displayed.



“Cleaning according to time” function removed

The “Cleaning according to time” function was removed from the service menu - machine data. This function was adopted in the SC Club from other machine types. However, since this does not fit the cleaning concept (Connect & Clean) of the SC Club, this function does not make sense for the SC Club and it was removed.

Important technician's note:

Should you be using this function in one of your machines, you must deactivate it **WITHOUT FAIL** before installing the new software version. If the function is not deactivated, the previously programmed cleaning time can no longer be changed after the software update since the menu item is no longer available.

Service > Machine data > Cleaning > Cleaning mode -> Cleaning according to time

Scroll bars added to various menus

If a USB stick with more than 17 saved files is used in an SC Club, previously only the first 17 files were displayed on the machine for selection and it was not possible to select a file which was farther down in the list.

A scroll bar was implemented in the affected menus with the new software.