

|  |                                 |
|--|---------------------------------|
| <b>T.I. no.: 2018 - 20</b><br>Updated: - | <b>Topic: SCP Software 2.74</b> |
|--|---------------------------------|

|                                    |                 |                                |
|------------------------------------|-----------------|--------------------------------|
| <b>Date: 03.09.2018</b>            | <b>Priority</b> | <b>Need for action</b>         |
| <b>Affected machines: SCP</b>      | High            | As soon as possible            |
| <b>From serial number: 1835../</b> | X Medium        | X On next visit to the machine |
| <b>As of date: -</b>               | Low             | FYI only                       |

## NEW FUNCTIONS AND IMPROVEMENTS

**The following is an overview of the new functions in 2.74:**

**New functions:**

- The beverage article number is used for telemetry and payment.
- Before a database is imported from a USB stick, the database is checked. Corrupt databases will no longer be imported.

**Improvements:**

- Various translation errors fixed.
- Wrong image for waste water info.
- For machines with a waste outlet, level monitoring is disabled via a factory setting.
- Screen calibration by the customer no longer available.
- Incorrect designation of "Powder system, left" for the service counter corrected.
- Text size in status line and quick info enlarged.
- The "Switch milk system on/off" function will be assigned to the "Operator" profile and can therefore be protected.
- VendRequest will be correctly forwarded to DIVA2 for "Free coupons".
- Beverages which have the price 0.00 are correctly detected (DIVA).
- More than two token channels are supported.
- Unspecified credit is detected correctly, but not shown.
- Beverage dispensing in self-service mode will always be correctly started.
- Changeover to milk powder with an empty fresh milk tank functions correctly.
- If the machine is switched off after cleaning with the milk system activated, the milk system does not have to be re-started manually.
- With activated payment system and MDB protocol, "Free Vend" will no longer be shown on the display.
- Faulty MDB initialisation no longer blocks the machine being started. This means MDB can be disabled in the Service menu.
- Speed of communication between modem and coffee machine increased.

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.