

T.I. no.: 2019 - 23 Updated: -	Topic: Solid state relay SCP
-------------------------------------------------	-------------------------------------

Date: 26.11.2019	Priority	Need for action
Affected machines: SCP	High	As soon as possible
From serial number: 1929 /	Medium	On next visit to the machine
As of date: —	X Low	X FYI only

IMPROVEMENTS

(SSR) solid state relay

To avoid a cost increase, **072 615** will be replaced by (SSR) solid state relay **072 044**.

This technical change concerns the following machines

- SCP Schaefer Coffee Prime

IMPORTANT

First installation of new relays

Since the new relays **072 044** do not fit on the old bracket, the complete assembly must be replaced when new relays are installed for the first time.

In other words, remove the old assembly (bracket and relay), install the new assembly (new bracket with new relays).

SSR SOLID STATE RELAY
072 615 OLD





SSR SOLID STATE RELAY
072 044 NEW



First installation of new relays in the SC Prime

- Replace relay assembly **074 535**. (Remove the old bracket with the old relays).
- Install new relay assembly **074 535**. (Install the new bracket with the new relays).



NEW RELAY MODULE **074 535**

NOTE

The Schaerer Coffee Prime is now equipped with two SSR 072 044, the predecessor had only one SSR installed.