

T.I. no.: 2019 - 32 Updated: -	Topic: SC Club – Product optimisation bean hopper insulation
---	---

Date: 12.12.2019	Priority	Need for action
Affected machines: SC Club	High	As soon as possible
From serial number: 27723	X Medium	X On next visit to the machine
As of date: -	Low	FYI only

REASON FOR CHANGE

As part of the internal bean hopper is located directly above the steam boiler, the beans inside heat up and this can affect the quality of the beverage.

In addition to the existing boiler insulation, the newly introduced insulation mat – which is fitted between the steam boiler and the bean hopper – protects the coffee beans from the heat radiated by the steam boiler.

IMPROVEMENT / SERIES SOLUTION:

The insulation has been introduced into series production from serial number **27723** onwards.

Spare part:

33.4287.5000 – Bean hopper insulation

The insulation can be ordered via the online spare parts catalogue or the online shop.

TECHNICIAN INFORMATION

If you receive any complaints relating to this matter, the insulation can simply be retrofitted to machines in the field.

