

T.I. no.: 2015 - 10 Updated: -	Topic: Software V2.31
-----------------------------------	-----------------------

Date: 23/09/2015	Priority	Need for action
Affected machines: SCP	High	As soon as possible
From serial number: 1512...	X Medium	X On next visit to the machine
As of date: CW 37	Low	FYI only

SOFTWARE V2.31

New functions

Cleaning

- **Startup flushing** for NcFoamer so that it only has to be **replaced every 5 days**.
The NcFoamer is flushed with 10 ml of milk. The startup flushing currently cannot be deactivated - this will be made possible in a future version.

Operation

- The software is now also available in Romanian.
- In order to completely remove the remaining milk from the milk system after dispensing a product, the air pump is activated repeatedly.

Adaptations

Operation

- Messages in the error statistics are no longer displayed repeatedly.
- Touch calibration request removed.
- Beverages configured in 2StepMode are displayed in the self-service mode.
- Images for self-service are kept after the update.

Beverage dispensing

- Optimised relief function to prevent spraying into the drip tray.
- Cappuccino preparation optimised.
- Mixer product is terminated if the water flow is too low.

Cleaning

- Stopping during cleaning corrected.
- Display of texts during cleaning optimised.
- NcFoamer cleaning process adapted.



The software and programming instructions can be downloaded in the Media Centre (www.schaerer.com/member) (login required).

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se ha dejado en blanco intencionalmente