

T.I. no.: 2016 - 03 Updated: -	Topic: New SSR position
---	--------------------------------

Date: 16/02/2016
Affected machines: SCP
From serial number: 1549...
As of date: CW 49/2015


Priority	
	High
	Medium
X	Low

Need for action	
	As soon as possible
	On next visit to the machine
X	FYI only


OVERVIEW

The position of the SSR in the machine was changed in CW 49/2015. The SSR is now on the left next to the power board and is screwed onto a holder on the housing. Access to the boilers and water protection have been improved with the new position.

NOTE
Existing machines cannot be retrofitted.



SSR position as of CW 49/2015



SSR position up to CW 48/2015

The "SSR relay cpl." assembly with article number 072516 for the SCP up to production date 48/2015 (1548...) no longer exists and can no longer be ordered. If an SSR is defective, a new one can be ordered separately.

The new article number of the "SSR relay cpl." assembly for the SCP from production date 49/2015 (1549...) is 074535.

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se ha dejado en blanco intencionalmente