

T.I. no.: 2021 - 04 Updated: -	Topic: SCA software 6.40
-------------------------------------------------	---------------------------------

Date: 08.03.2021	Priority	Need for action
Affected machines: SCA	High	As soon as possible
From serial number:	Medium	X On next visit to the machine
As of date:	X Low	FYI only

IMPROVEMENTS

Software troubleshooting

The following issues have been resolved in **software version 6.40**.

- Error in MBD payment system, the badge was not detected or "Sales error" was shown
- Editing of the article number of the payment card is not possible in CCI/CSI via PLU code
- Display after a software update in incorrect language
- Losing the naming of tabs after a software update
- Blockage of the coffee machine after rinsing in eco mode
- Brewing motor overcurrent" error during the initialisation of the coffee machine