

T.I. No.: 2021-10 Updated: -	Topic: Replacing the control panel (touch screen)
---	--

Date: 01.04.2021
Affected machines: SC Club
From serial number: -
As of date: immediately

Priority
High
Medium
x Low


Need for action
As soon as possible
On next visit to the machine
x FYI

GENERAL INFORMATION

Replacing the control panel (touch screen)

The SC Club control panel is supplied fully wired, consisting of control panel (1), USB cable (2) and ribbon cable (3).

In case of a warranty claim, the control panel including the cables must be returned to Schaeerer AG. The warranty will expire if the cables have been dismantled and are missing.



Position	Naming	Article number
1	Control panel SC Club (Touch screen)	33.4066.1000 33.4066.1299 (Successor model)
2	USB cable	33.4167.0000
3	Ribbon cable	33.4156.9000