

<b>T.I. no.: 2021-21</b> Updated: -	<b>Topic: Withdrawal Temporary Change of Grinding Disks</b>
--	---

<b>Date: 20.07.2021</b>	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines: SC Club</b>	High	As soon as possible
<b>From serial number: 52281</b>	X Medium	X On next visit to the machine
<b>As of date: immediately</b>	Low	FYI only

## IN-HOUSE MANUFACTURED GRINDING DISKS

We would like to inform you today that the temporary changeover to our own grinding discs at the SC Club has been reversed. Series production has been switched to the original grinding discs.

### Reason for Change

Due to a supply bottleneck at the supplier of the grinding discs, you were informed in the TechInfo 2021-14 about a temporary change to manufactured grinding discs for the new SC Club coffee machines delivered ex works.

As the supply of the grinding discs used for the SC Club is now guaranteed again by the supplier, the temporary change to manufactured grinding discs will be withdrawn.

### Serial- and Spare Part Solution

With the following serial numbers, the SC Club will again be delivered with the conventional grinding discs:

Serial number:

- 52281 – 52282
- 52583 – 52590
- 52635 – 52638
- 52690 – 52706
- 52719 – 52746
- 52752 – 52756
- 52777 – 52800
- 52819 und ff.

The following grinders are affected by the change:

- Grinder left Espresso
- Grinder right Café Crème

### Advice for Technicians

The adjustment of the standard parameters of the portioner calibration in the customer/service memory described in Tech Info 2021-14 has also been stopped with the withdrawal of the change.