

<b>T.I. no.: 2022-02</b> Updated:	<b>Topic: SPCC Software V4.34.7</b>
--------------------------------------	-------------------------------------

Date: 26.01.2022	Priority	Need for action
Affected machines: SPCC	High	As soon as possible
From serial number: -	X Medium	X On next visit to the machine
As of date: Immediately	Low	FYI only

## INFORMATION ON SOFTWARE UPDATE

The new software update V4.34.7 eliminates bugs, optimises the platform software and replaces the software version V4.32.5.

### Overview Features

- > Software driver for new MR node with milk scales

### Overview Bugfix

- > Malfunction when recognising the BestFoam mixer
- > Malfunction with Supersteam without milk system
- > Water flow error leads to descaling abort
- > Recognition error with SD card not present
- > Incorrect price transmission to the payment system