

<b>T.I. no.:</b> 2023-04 <b>Updated:</b>	<b>Topic:</b> SCS   SOUL Software V4.44.11
---	--

<b>Date:</b> 06.02.2023	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines:</b> SCS / SOUL	High	As soon as possible
<b>From serial number:</b> -	x Medium	x On next visit to the machine
<b>As of date:</b> immediately	Low	FYI only

## INFORMATION ON SOFTWARE-UPDATE

**Installation note**

For SOUL machines without BestFoam, with Supersteam, the previous software version V4.38.11 must be used. The software update V4.44.11 must not be executed.

The new software update V4.44.11 eliminates bugs, optimises the platform software and replaces the software version V4.38.11.

### Overview Features

- Hardware configuration: group actuators/sensors according to CAN nodes
- Hardware detection: improved troubleshooting through component overview per detection step (grouping of parameters for the HCU module)
- Various software default values per machine type after master reset and during initial commissioning
- Eject and regrind when grinder is empty
- Individual recipe settings for alternative coffee blend
- Import function of nutritional data via JSON file (not for SCS)
- Pricing for additional ingredients (not for SCS)
- NTC as milk empty sensor (functionality from NTC milk system)
- No milk rinse when service technician login is active

**Information on further documentation**

Further information can be found in the SCS/SOUL training documentation from Technical Support. This can be downloaded from the <Schaerer Coffee Link> portal in the Media Pool.

Title: Training Modules / Reference Manual

Issue: V16 | 02.2023

Language:

- enGB (from CW07)
- deDE, zhCN and zhTW (from CW08)

**Service Contact**

**Global Technical Support Team**

GBU Professional Coffee Maschines

- > Support Hotline: +41 32 681 62 75 (10:00-11:30 CET/ 15:00-16:30 CET)
- > Support E-Mail: technical-support@schaerer.com