

<b>T.I. no.:</b> 2023-10 <b>Updated:</b>	<b>Topic:</b> SCS   SOUL Software V4.54.6
---	---

<b>Date:</b> 05.04.2023	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines:</b> SCS / SOUL	<input type="checkbox"/> High	<input type="checkbox"/> As soon as possible
<b>From serial number:</b> -	<input checked="" type="checkbox"/> Medium	<input checked="" type="checkbox"/> On next visit to the machine
<b>As of date:</b> immediately	<input type="checkbox"/> Low	<input type="checkbox"/> FYI only

## INFORMATION ON SOFTWARE-UPDATE

The new software update V4.54.6 eliminates bugs, optimises the platform software and replaces the software version V4.44.11.

### Overview of the most relevant new features

- In-export of 'configuration packages' (which include media packages)
- Powder calibration to facilitate nutritional information for beverages that contain powder
  - > only relevant when using the nutritional information
  - > no effect on the beverage settings
- Blinking of the status lights for five seconds prior outlet rinsing
  - > Frequency (on/off): 250ms
  - > Colour: yellow
- Telemetry feature: remote update of the menu card including all recipes (transfer of individual recipes is currently impossible)
- Utilities (service menu) expanded with 'steam boiler pressure test'
- ProCare: Various cleaning schedule optimisations / Last mile cleaning (with Plug & Clean) enforced / new parameter 'reset pouch counters' in the service menu
- Parameter 'outlet cover' in the 'undetectable' section of the hardware detection
  - > default = 'on' (animation shown during the cleaning)
  - > 'off' for special machine versions (Soul C for the US)

### Corrections/fixes issues

- Flavour point cleaning is fully restored
- Control of valve V25 is restored
  - > 3/2 way valve for Super Steam with Best Foam or
  - > 2/2 way valve for Super Steam without Best Foam
- Grinder calibration value was not processed by the software (unless a manual restart was made).

**Service Contact**

**Global Technical Support Team**  
 GBU Professional Coffee Machines  
 > Support Hotline: +41 32 681 62 75 (10:00-11:30 CET/ 15:00-16:30 CET)  
 > Support E-Mail: technical-support@schaerer.com