

T.I. no.: 2024-7 Updated: -	Topic: New article number for the SKYE mixing cup
--	--

Date: 10.06.2024
Affected machines: SKYE
From serial number: -
As of date: Immediate

Priority and need for action	
<input type="checkbox"/>	High: as soon as possible
<input type="checkbox"/>	Medium: on next visit to the machine
<input checked="" type="checkbox"/>	Low: FYI only

DESCRIPTION

Mixing cup **33.2895.4000** has been optimised with a stop rib near the outlet nozzle. Due to this change, a new article number has been created for the SKYE mixing cup: **101963**.

Distinguishing features of mixing cup




Figure 1: Mixing cup **101963** without stop rib




Figure 2: Mixing cup **33.2895.4000** with stop rib

Spare parts

When spare parts are needed for the SKYE, mixing cup with article number **101963** must be ordered from now on.

More information

For more information on the affected machines, contact **Technical Support**:

Service contact

Global Technical Support Team
GBU Professional Coffee Machines

- > Support hotline: +41 32 681 62 75 (10:00-11:30 a.m. CET/ 3:00-4:30 p.m. CET)
- > Support e-mail: technical-support@schaerer.com