

<b>T.I. no.: 2024-09</b> Updated: -	<b>Topic: Omission of retrofitting set mod. 03 from maintenance set WS 2</b>
--	--

<b>Date: 10.07.2024</b>	<b>Priority and need for action</b> <input type="checkbox"/> High: as soon as possible <input type="checkbox"/> Medium: on next visit to the machine <input checked="" type="checkbox"/> Low: FYI only
<b>Affected machines: SC Club</b>	
<b>From serial number: 51987</b>	
<b>Start date: immediately</b>	

This technical information is intended to provide trained service technicians with machine-specific information.

	<b>WARNING</b>
	<b>Risk of injury due to insufficient qualification!</b> Improper handling can lead to personal injury and property damage. Service and maintenance work on coffee machines and their accessories in particular requires appropriate knowledge of electrical engineering, mechanics and hydraulics. <ul style="list-style-type: none"><li>▶ All work may only be carried out by qualified staff.</li><li>▶ If you do not have this knowledge, please contact trained service staff.</li></ul>

## Reason for change

In **Technical Information 2021-16**, we informed you of **machine modification 03** as well as the temporary adaptation of the maintenance set.

The maintenance set was temporarily adapted and retrofitting set **modification 03 – brewing valve** was added. This made it possible to convert machines in the field to **machine modification 3** in the framework of **maintenance 2**.

With the assumption that **maintenance 2** was done at least once on the machines in the field in the past time frame, we are withdrawing the temporary adaptation of the maintenance set.

## Field and spare parts solution

Omission of retrofitting set **modification 03 – brewing valve** in maintenance set **WS 2**

**33.4744.7000** – Maintenance set **WS 2**

**33.3335.1000** – Retrofitting set **modification 03 – brewing valve**

## Note for technicians

If you have machines in your area that have not yet been converted to **modification 03**, the retrofitting set can still be ordered in the ways you are familiar with.

**Technical Information 2021-16** is attached in the following to clear up any uncertainty.

<b>T.I. no.:</b> 2021-16 <b>Updated:</b>	<b>Topic:</b> Retrofit kit „Modification 3 Brewing Valve“
---	---

<b>Date:</b> 17.06.2021	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines:</b> SC Club	High	As soon as possible
<b>From serial number:</b> 51987	X Medium	X On next visit to the machine
<b>As of date:</b> immediately	Low	FYI only

## PRODUCT OPTIMISATION



As of now, the retrofit kit „Modification 3 Brewing Valve“ will be available in the context of product optimisation MOD.3, with which the linked brewing valve will be replaced by a single valve.

With this modification, the connection hoses are shortened and thus, the temperature loss due to cooling of the first beverage after longer dispensing pauses can be reduced.

The focus here is on beverages with a low filling quantity, such as, for example, espresso.

The retrofit kit can be ordered immediately under item no. 33.3335.1000 and will also be part of the maintenance kit in the future.

Hereby it is assured that, at the latest with the next maintenance, the machines in the field will also be equipped accordingly.

In the next step, the product optimisation will be integrated into the production process so that the modification will already be fitted ex works. As soon as the production process has been changed, a further product information will follow.