

# SERVICE MEMO

07-11-2024

Dispenser(s): *Kometa*  
Title: Drip tray presents sensor

## Background:


The presence of the Kometa drip tray is recognised by a sensor, which is activated by a magnet on the drip tray.

In the first production machines Evoca found out the drip tray was recognized even if it was not in the proper position with leakage under machine as result. So, Evoca moved the sensor further away from the drip tray to be sure the end user/operator would position the drip tray in the right position.


First production Evoca:



Production for JDE:



**If the drip tray is not recognized correctly, the sensor can be adjusted by pulling it towards the drip tray (around 5mm):**



Name: J. Verdam

