

| | | | |
|---------------------------------------|--------------------------------------|-----------------------------|--------------------------------|
| Type Coffee Vending Machine | Model 9100 | N° T.I. 03 - 2021 | |
| Serial Number 13521476 | Subject TOUCHSCREEN UPDATE | ISSUED FOR (X) | Action Information X |

REASON:

Due to a production process optimization at the supplier

MODIFICATIONS:

A new Touchscreen version has been released with a **new System key 3.0.10-1**

New Touchscreen Spare
part code: **264505**
SAP: **55124236**

Pre-modification Touchscreen
Spare part code: **260321**



Important note:

- **WARNING!** DO NOT downgrade a new TS to a System Key lower than 3.0.10-1.
- It's possible to upgrade a pre-modification touchscreen to the System Key 3.0.10-1 (or higher), even if it's not mandatory.

➤ Machines concerned by modification from S/N **13521476**.