



Type OCS	Model MAGIC	N° T.I. 08 - 2023				
Serial 9023MGCP012082	Subject MODIFICATION OF CAPPUCCINATORE LID	ISSUED FOR (X) <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action						
Information	X					

REASON:

Improved positioning of the machine dispenser assembly

MODIFICATIONS:

In order to improve the positioning of the dispenser in the machine, we modified the lid of the cappuccinatore by inserting two mold ribs. We have seen that this modification also improves the coupling between the cappuccinatore and the front of the machine, fixing the remaining cases of lack of cappuccinatore presence signal.



Spare part code CAPPUCCINATORE LID: **265457** sap 55126491

➤ **Machines concerned by modification from S/N: 9023MGCP012082**

EXCHANGEABILITY:
Spare code: **265457**