

T.I. no.: 2017 - 24 Updated: -	Topic: SC Soul Software 2.02
--	-------------------------------------

Date: 07.11.2017	Priority	Need for action
Affected machines: SC Soul	High	As soon as possible
From serial number: 1740../	X Medium	X On next visit to the machine
As of date: -	Low	FYI only

NEW FUNCTIONS AND IMPROVEMENTS

The following is an overview of the new functions and fixed errors:

New functions:

- Pin query for access to the service menu can be activated.

Improvements

- Various translation errors fixed.
- Various adjustments made to the GUI.
- Additional currency added (ZAR, "No currency")
- Names of hardware components in hardware detection are correctly displayed.
- The cleaning log is correctly stored during every cleaning.
- The commissioning animation is displayed correctly.
- The remaining credit for the coin changer is correctly accounted for.
- Time difference for the timer setting has been fixed.
- Coffee beverages are correctly detected in the beverage statistics.
- A missing time zone setting for commissioning no longer leads to an error.
- Maintenance counters are correctly reset during commissioning.
- Incorrect counter statistics for powder beverages corrected.
- IP and MAC addresses are displayed in the Quickinfo.
- Automatic logout in the settings has been fixed.
- Interruptions in Best Foam process have been fixed.
- Faulty machine behaviour when pulling out the grounds drawer during beverage dispensing has been fixed.
- Accounting system for mixed credit operation works correctly.
- When the payment system is activated, beverages with a 0.00 amount are correctly detected.
- PLU for payment with MDB payment system is correctly detected.
- Faulty cappuccino preparation fixed.
- Information for checking the water drain before descaling has been adjusted.
1 litre must be able to drain in 30 seconds, instead of 1.1 litre in 45 seconds as before.
- Invalid error messages when starting the machine have been fixed.

Pin query for access to the service menu can be activated

In the "Configuration" -> "Operating mode" -> "Service menu access" menu, access to the service menu can be protected by a PIN.

Activate access with PIN and define the desired PIN. The change is active after a restart.

