

T.I. no.: 2019 - 30 Updated: -	Topic: Schaerer Barista – Software version 2.2.2
---	---

Date: 12.12.2019
Affected machines: Schaerer Barista
From serial number: -
As of date: -

Priority	
	High
	Medium
X	Low

Need for action	
	As soon as possible
	On next visit to the machine
X	FYI only


NEW FUNCTION

Display portafilter removal

We are still getting reports from the field stating that users are removing the portafilter too soon after beverage dispensing and this is resulting in avoidable service visits.

In order to provide users with an extra visual aid in addition to the existing warning tone, this software makes it possible to use background colours in the display to tell the user when it is time to remove the portafilter.


Display during beverage dispensing




Display shortly after beverage dispensing



Display indicating that the portafilter can be removed



Menu navigation: System > Control options > Display portafilter removal



The new software was tested during an extensive internal approval test.

If, however, problems do occur during the update, please save the data on a USB stick, copy it into an e-mail and send it to Schaerer AG together with a detailed description of the problem.

Please use the following e-mail address: MSAG_Tech-Support-INT@schaerer.com