

## Service Memo

2019-007

Machine: Schaerer Coffee Soul  
Titel: Schaerer Coffee Soul O-ring and V-seal mixing bowl instant product

---

Dear All,


Hereby I want to inform you that the numbers mentioned in the maintenance list for the Schaerer Coffee Soul for the instant mixer are not correct.

The wrong numbers are:

Pos 1 55101034 33.1587.4000 Seal, mixer motor  
Pos 2 55101033 33.2381.7000 Seal, mixer chamber

The right numbers are:

Pos 1 55121228 078995 V-RING RD FOR MIXING CUP  
Pos 2 55121229 078996 O-RING RD MIXER MOTOR



The maintenance list for the Schaerer Soul is also updated.