

T.I. No.: 2021-11 Updated: 21.04.2021	Topic: Product optimisation - combination level sensor
-------------------------------------------------	---------------------------------------------------------------

Date: 16.04.2021
Affected machines: SC Club
From serial number: 49246
As of date: immediately

Priority	
	High
X	Medium
	Low

Need for action	
	As soon as possible
X	On next visit to the machine
	FYI

REASON FOR CHANGES

A new, modified and also improved combination level sensor was introduced for the SC Club.

The following advantages are achieved through this standardisation:

- Improved measuring sensor technology -> larger measuring field and measuring tolerances
- More stable function in case of disturbing influences from the environment -> gap mass, contamination...
- Universal use with multiple machine types, e.g. the SC Club
- Simplified spare parts procurement and stock-keeping

Differentiation of the combination level sensor:

NEW SENSOR (BLUE)
33.4244.8000



PREVIOUS SENSOR (GREEN)
33.4066.2000

