

T.I. no.: 2021-27 Updated: 26.10.2021	Topic: SCS / SOUL Software V4.32.5
---	---

Date: 22.10.2021	Priority	Need for action
Affected machines: SCS / SOUL	High	As soon as possible
From serial number: 2140..	X Medium	X On next visit to the machine
As of date: Immediately	Low	FYI only

INFORMATION ON SOFTWARE UPDATE

The new software update V4.32.5 eliminates bugs, optimises the platform software and replaces the software version V4.30.9.

IMPORTANT NOTE

The software update V4.32.5 must not be carried out on SOUL machines with a billing system. At the current time, the functionality with regard to coin acceptors cannot be guaranteed.

Overview Features

- > New hardware detection that has been functionally revised.

An overview and details will be communicated in a subsequent Tech Info in due course.