

T.I. no.: 2022-01 Updated:	Topic: SCS / SOUL Software V4.34.7
---	---

Date: 26.01.2022	Priority	Need for action
Affected machines: SCS / SOUL	High	As soon as possible
From serial number: -	X Medium	X On next visit to the machine
As of date: Immediately	Low	FYI only

INFORMATION ON SOFTWARE UPDATE

The new software update V4.34.7 eliminates bugs, optimises the platform software and replaces the software version V4.32.5.

Overview Features

- > Software driver for new MR node with milk scales

Overview Bug-Fixes (Platform)

- > Malfunction when recognising the BestFoam mixer
- > Malfunction with Supersteam without milk system
- > Water flow error leads to descaling abort
- > Recognition error with SD card not present
- > Incorrect price transmission to the payment system