

T.I. no.: 2022-18 Updated:	Topic: SPCC Software V4.38.11
--------------------------------------	--------------------------------------

Date: 13.07.2022	Priority	Need for action
Affected machines: SPCC	High	As soon as possible
From serial number: -	X Medium	X On next visit to the machine
As of date: Immediately	Low	FYI only

INFORMATION ON SOFTWARE UPDATE

The new software update V4.38.11 eliminates bugs, optimises the platform software and replaces the software version V4.34.7.

Overview Features

- > Allergy & nutrition information
- > Maintenance counter adapted to the maintenance concept

Overview Bugfix

- > Incorrect display of the serial number in the system info
- > Incorrect price display for drinks with several drink sizes

Service Contact

Global Technical Support Team
GBU Professional Coffee Machines

- > Support Hotline: +41 32 681 62 75 (10:00-11:30 CET/ 15:00-16:30 CET)
- > Support E-Mail: technical-support@schaerer.com