

T.I. no.: 2024-18 Updated: -	Topic: New Best Foam blender
---	-------------------------------------

Date: 4/30/2025
Affected machines: SOUL 10-12 / SCS / Coffee Art Plus Best Foam
From serial number: 4010006182
From date: from 2/17/2025

Priority and need for action	
<input type="checkbox"/>	High: as soon as possible
<input type="checkbox"/>	Medium: on next visit to the machine
<input checked="" type="checkbox"/>	Low: FYI only

NEW BEST FOAM BLENDER

A new Best Foam blender with number **3329892100** is available for the SOUL 10-12, SCS and Coffee Art Plus Best Foam machines. The material that was previously used for making the Best Foam blender is no longer available.

Replacing Best Foam blender

Replace the old Best Foam blender with number 3329281200 with the new Best Foam blender with number **3329892100**.

	NOTE
	Combining parts of the old and new Best Foam blender Parts of the old blender must not be combined with the new blender as they are not compatible.

Best Foam blender old 3329281200




Figure 1: Best Foam blender old

Best Foam blender new 3329892100




Figure 2: Best Foam blender new

More information

For more information, contact **Technical Support** at:

Service contact
Global Technical Support Team GBU Professional Coffee Machines
> Support hotline: +41 32 681 62 75 (10:00-11:30 a.m. CET/3:00-4:30 p.m. CET)
> Support e-mail: technical-support@schaerer.com