



SERVICE MEMO

3-11-2023

Number: JDE 2023-08
 Dispenser(s): SOUL 10-12 self service
 Title: 'hole' by second squeeze valve milk hose

With this service memo I would like to inform you that for the SOUL Self Service machine with the next serial numbers it is possible that you find a 'hole' on the place for the second squeeze valve for the milk hose like on the picture below. Black part will have the foil as shown on the right side.



This doesn't affect the working of the machine but is done in consultation with JDE.

Machine configuration is a 'real' SOUL Self Service machine.

Affected serial numbers:

2340679963	2341682228	2341682238	2341682248	2341682258	2341682268	2341682279
2340679964	2341682229	2341682239	2341682249	2341682259	2341682270	2341682280
2340679965	2341682230	2341682240	2341682250	2341682260	2341682271	2341682281
2340679966	2341682231	2341682241	2341682251	2341682261	2341682272	2341682282
2340679967	2341682232	2341682242	2341682252	2341682262	2341682273	2341682283
2340679968	2341682233	2341682243	2341682253	2341682263	2341682274	2341682284
2340679969	2341682234	2341682244	2341682254	2341682264	2341682275	2341682285
2340679970	2341682235	2341682245	2341682255	2341682265	2341682276	2341682286
2341682226	2341682236	2341682246	2341682256	2341682266	2341682277	2341682287
2341682227	2341682237	2341682247	2341682257	2341682267	2341682278	2341682288
						2341682269

Name: Bart Bakker



